

## Wired barcode scanner quickly restore factory Settings

Applicable to ScnaHome brand Wired series products

Make sure to follow the instructions in the document

# Wired USB interface factory data reset



First step



USB KBW (Second step)

# Wired RS232 Serial port / TTL / 485 interface factory data reset



First step



RS232 Serial port / UART / TTL / 485  
(Second step)

## Baud rate setting



9600bps



38400bps



19200bps



115200bps

# Wired Network / WiFi interface factory data reset



First step



Second step



Third step